

## **Features**

- Locks all doors on body side with one padlock per side. Padlock not included.
- New MLS design with two-part rod assembly has streamlined manufacturing and installation (see Bulletin P2127)
- Spring-assist is now standard (spring is detachable), and provides smooth operation with low efforts
- Strength of locking system increased more than 50%, providing additional compartment security
- New part numbers for handling RFC or #2 configurations (see below)
- Retrofitting of pre-built bodies is straightforward (minor changes required on bodies prior to s/n A35435)\*\*

BODY MLS PART #	INSTALLATION PART #	BODY MODEL #
BMLS75 BMLS80 BMLS96 BMLS108 BMLS108C BMLS132 BMLS132C BMLS132C BMLS144 BMLS156 BMLS156 BMLS156C BMLS168	BINSTMLS75 BINSTMLS80 BINSTMLS96 BINSTMLS108 BINSTMLS132 BINSTMLS132 BINSTMLS132C BINSTMLS144 BINSTMLS156 BINSTMLS156 BINSTMLS156 BINSTMLS156C BINSTMLS168 BINSTMLS168	(37CA bodies: L, S, T) (40CA & 42CA bodies: L, S, T, J, & U) (56CA & 57CA bodies: L, S, T, J, & U) (60CA bodies: L, S, T, J, U, E, & G) (60CA bodies: C) (84CA bodies: L, S, T, J, U, E, & G) (84CA bodies: C) (102CA bodies: E) (108CA bodies: L, S, T, J, U, & E) (108CA bodies: C) (120CA bodies: L, S, T, J, U, & E) (120CA bodies: C)
RFC MLS PART #	RFC INSTALLATION PART #	APPLICATION
BMLSRFC (1 required per side)	BINSTMLSRFCC BINSTMLSRFCS	Curbside Raised Front Compartment Streetside Raised Front Compartment
#2 DOOR MLS PART# BMLS-2 (1 required per side)	#2 DOOR INSTALLATION PART # BINSTMLS-2C BINSTMLS-2S	APPLICATION  Curbside Installation for #2 door configuration Streetside Installation for #2 door configuration

## **BODY SIDES ONLY**

BODY SIDE MLS PART #	BODY SIDE MODEL	INSTALLATION PART #
BMLS96SD1 BMLS108SD1	(40CA & 42CA body side only: L, S, T, J & U) (56CA & 57CA body side only: L, S, T, J & U) (60CA body side only: L, S, T, J, U, E & G) (84CA body side only: L, S, T, J, U, E & G)	Choose the part # based on the side BINSTMLSSD1C(For curbside body side) BINSTMLSSD1S(For Streetside body side)

<sup>\*\*</sup>Bodies prior to S/N# A35435 will require some modifications to the door panel to work with this new MLS system. Please consult RKI for further details.